



LEADING EDGE *and* ***POST FORMED*** ***WORKTOPS***

It is important that all worktops are inspected before fitting commences.

Always check for damage or any defects both on the flat surface and along the edges for colour shading and dimensions.

When using more than one worktop, always check the colour match for any possible variations in shade and also check dimensions of each top before fitting.

Mica Post Form cannot be responsible for any refitting charges resulting from imperfections which may have existed before fitting.